

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start		Rating **	A	Issue No.	<b>5</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD0108_01_s_2013_5				
Comment Code					
Inspector Comment					
RD 108 has O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	<b>7</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD0108_01_s_2013_7				
Comment Code					
Inspector Comment					
RD 108 maintains a stockpile of flood response materials.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start		Rating **	A	Issue No.	<b>9</b>
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_RD0108_01_s_2013_9				
Comment Code					
Inspector Comment					
RD 108 has written response plans and regular flood response training.					

No Photos

LM Start	<b>0.06</b>	Rating **	M	Issue No.	<b>38</b>
LM End	<b>0.06</b>	Issue Type +	Ma	Location *	N/A
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.822897 °	38.822897 °	
			-121.797000 °	-121.797000 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37608 DS_ID:17943 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: 1 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959 FS Date: 6/10/2014					

Photo 1 of 3 : UCIP\_SP\_2017\_37608\_68207.jpg



View of concrete structure visible on waterward side.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	38 (cont)
LM End	0.06	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822897 °	38.822897 °
				-121.797000 °	-121.797000 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37608					
DS_ID:17943					
EP_NO: 9396					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon.					
FIELD_STRUCT_DESC: 1 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959					
FS Date: 6/10/2014					

Photo 2 of 3 : UCIP\_SP\_2017\_37608\_68210.jpg



Dense vegetation on waterward side.

LM Start	<b>0.06</b>	Rating **	M	Issue No.	<b>38 (cont)</b>
LM End	<b>0.06</b>	Issue Type +	Ma	Location *	N/A

Photo 3 of 3 : UCIP\_SP\_2017\_37608\_68208.jpg



View of concrete structure visible on landward side.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	39
LM End	0.06	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822919 °	38.822919 °
				-121.797046 °	-121.797046 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37609					
DS_ID:22386					
EP_NO: 9396					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon.					
FIELD_STRUCT_DESC: 2 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959					
FS Date: 6/10/2014					

Photo 1 of 3 : UCIP\_SP\_2017\_37609\_68211.jpg



Concrete structure located on waterward side.

LM Start	<b>0.06</b>	Rating **	M	Issue No.	<b>39 (cont)</b>
LM End	<b>0.06</b>	Issue Type +	Ma	Location *	N/A

Photo 2 of 3 : UCIP\_SP\_2017\_37609\_68215.jpg



Dense vegetation covers the waterward slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	39 (cont)
LM End	0.06	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822919 °	38.822919 °
				-121.797046 °	-121.797046 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37609 DS_ID:22386 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: 2 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959 FS Date: 6/10/2014					

Photo 3 of 3 : UCIP\_SP\_2017\_37609\_68213.jpg



View of concrete structure located on landward side.

LM Start	0.06	Rating **	M	Issue No.	40
LM End	0.06	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822933 °	38.822933 °
				-121.797081 °	-121.797081 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37610					
DS_ID:22387					
EP_NO: 9396					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon.					
FIELD_STRUCT_DESC: 3 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959					
FS Date: 6/10/2014					

Photo 1 of 3 : UCIP\_SP\_2017\_37610\_68216.jpg



Concrete structure located on waterward side.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	40 (cont)
LM End	0.06	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822933 °	38.822933 °
				-121.797081 °	-121.797081 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37610 DS_ID:22387 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: 3 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959 FS Date: 6/10/2014					

Photo 2 of 3 : UCIP\_SP\_2017\_37610\_68219.jpg



Dense vegetation covers waterward side slope.

LM Start	<b>0.06</b>	Rating **	M	Issue No.	<b>40 (cont)</b>
LM End	<b>0.06</b>	Issue Type +	Ma	Location *	N/A

Photo 3 of 3 : UCIP\_SP\_2017\_37610\_68217.jpg



Concrete structure located on landward side.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	41
LM End	0.06	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822897 °	38.822897 °
				-121.797000 °	-121.797000 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37611					
DS_ID:22388					
EP_NO: 9396					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon.					
FIELD_STRUCT_DESC: 4 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959					
FS Date: 6/10/2014					

Photo 1 of 3 : UCIP\_SP\_2017\_37611\_68220.jpg



Concrete structure located on waterward side.

LM Start	<b>0.06</b>	Rating **	M	Issue No.	<b>41 (cont)</b>
LM End	<b>0.06</b>	Issue Type +	Ma	Location *	N/A

Photo 2 of 3 : UCIP\_SP\_2017\_37611\_68224.jpg



Waterward slope covered by dense vegetation.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.06	Rating **	M	Issue No.	41 (cont)
LM End	0.06	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822897 °	38.822897 °
				-121.797000 °	-121.797000 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37611 DS_ID:22388 EP_NO: 9396 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon. FIELD_STRUCT_DESC: 4 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959 FS Date: 6/10/2014					

Photo 3 of 3 : UCIP\_SP\_2017\_37611\_68222.jpg



Concrete structure visible on landward side.

LM Start	0.07	Rating **	M	Issue No.	42
LM End	0.07	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822954 °	38.822954 °
				-121.797135 °	-121.797135 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37607					
DS_ID:22389					
EP_NO: 9396					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon.					
FIELD_STRUCT_DESC: 5 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959					
FS Date: 6/10/2014					

Photo 1 of 3 : UCIP\_SP\_2017\_37607\_68203.jpg



Concrete structure located on waterward side.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.07	Rating **	M	Issue No.	42 (cont)
LM End	0.07	Issue Type +	Ma	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.822954 °	38.822954 °
				-121.797135 °	-121.797135 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:37607					
DS_ID:22389					
EP_NO: 9396					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to contact owner to determine status of structure. Notes indicate crossing has been abandoned. Owner will need to coordinate with CVFPB and DWR inspector to determine how to properly abandon.					
FIELD_STRUCT_DESC: 5 of 5. Five 72-inch abandoned pipes or culvert through levee 31.6 feet below crown. Slide gates on both ends. (App. 9736-RD 108) Ramp on landward slope. (App.9396-RD). O&M Manual SAC 132; October 1959					
FS Date: 6/10/2014					

Photo 2 of 3 : UCIP\_SP\_2017\_37607\_68206.jpg



Waterward slope covered by dense vegetation.

LM Start	<b>0.07</b>	Rating **	M	Issue No.	<b>42 (cont)</b>
LM End	<b>0.07</b>	Issue Type +	Ma	Location *	N/A

Photo 3 of 3 : UCIP\_SP\_2017\_37607\_68204.jpg



Concrete structure located on landward side.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	0.10	Rating **	U	Issue No.	19
LM End	3.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.823151 °	38.842055 °
				-121.797639 °	-121.856554 °
DWR ID	DWR_RD0108_01_s_2017_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_19\_20170503\_00038.jpg



Tall grass on waterside levee slope, blocking visibility/ Spring 2017.

LM Start	0.10	Rating **	U	Issue No.	24
LM End	16.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.823151 °	38.984452 °
				-121.797639 °	-121.947592 °
DWR ID	DWR_RD0108_01_s_2017_24				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_24\_20170503\_00039.jpg



Tall grass on landside levee slope, blocking visibility. Spring 2017.

LM Start	1.48	Rating **	M	Issue No.	25
LM End	1.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.830839 °	38.831009 °
				-121.821321 °	-121.821821 °
DWR ID	DWR_RD0108_01_s_2017_25				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
150' sloughing section on landside levee slope. District will attempt to repair this site without USACE assistance.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_25\_20170503\_00040.jpg



View of sloughing on landside slope. Spring 2017.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	1.93	Rating **	M	Issue No.	27
LM End	1.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.833274 °	38.833486 °
				-121.829056 °	-121.829696 °
DWR ID	DWR_RD0108_01_s_2017_27				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
150' sloughing section on crown and landside levee slope. District will attempt to repair without USACE assistance.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_27\_20170503\_00041.jpg



View of sloughing on landside slope. Spring 2017.

LM Start	3.65	Rating **	M	Issue No.	23
LM End	3.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.842620 °	38.842620 °
				-121.858732 °	-121.858732 °
DWR ID	DWR_RD0108_01_f_2015_23				
Comment Code					
DE : Debris					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_23\_20170320\_00010.jpg



View of the debris on the waterward side of the levee. Fall 2015.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	3.97	Rating **	U	Issue No.	28
LM End	4.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.843293 °	38.843562 °
				-121.864588 °	-121.866885 °
DWR ID	DWR_RD0108_01_s_2017_28				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_28\_20170503\_00042.jpg



Tall grass on waterside levee slope, blocking visibility. Spring 2017.

LM Start	4.56	Rating **	U	Issue No.	30
LM End	20.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.844511 °	39.033933 °
				-121.875348 °	-121.993293 °
DWR ID	DWR_RD0108_01_s_2017_30				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_30\_20170503\_00043.jpg



Tall grass on waterside levee slope, blocking visibility. Spring 2017.

LM Start	5.92	Rating **	C	Issue No.	17
LM End	6.06	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.852230 °	38.853967 °
				-121.897211 °	-121.898571 °
DWR ID	DWR_RD0108_01_s_2016_17				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	8.27	Rating **	A/W	Issue No.	26
LM End	8.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Cracking			38.882595 °	38.882595 °
				-121.914669 °	-121.914669 °
DWR ID	DWR_RD0108_01_f_2015_26				
Comment Code					
CR1 : Monitor and have inspected by geotechnical engineer.					
Inspector Comment					
Cracking still visible, but appears to have closed up during winter season. Recommend monitoring.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_26\_20170320\_00011.jpg



View of the crack on the waterward side of the levee looking upstream.  
Suggest monitoring the crack. Fall 2015.

LM Start	8.98	Rating **	C	Issue No.	15
LM End	8.98	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.892912 °	38.892912 °
				-121.914636 °	-121.914636 °
DWR ID	DWR_RD0108_01_f_2016_15				
Comment Code					
GA : Garbage					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	9.17	Rating **	U	Issue No.	10
LM End	9.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.895605 °	38.896086 °
				-121.914645 °	-121.914646 °
DWR ID	DWR_RD0108_01_s_2017_10				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
200' section of multiple sloughs. District submitted request for PL 84-99 assistance.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_10\_20170503\_00044.jpg



View of sloughing on waterside slope. Spring 2017.

LM Start	9.30	Rating **	M	Issue No.	31
LM End	9.30	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.897494 °	38.897494 °
				-121.914680 °	-121.914680 °
DWR ID	DWR_RD0108_01_s_2017_31				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
100' sloughing section on waterside slope. District submitted application for PL 84-99 assistance.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_31\_20170503\_00045.jpg



View of sloughing on waterside slope. Spring 2017.

LM Start	11.20	Rating **	C	Issue No.	18
LM End	11.20	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.925037 °	38.925037 °
				-121.914509 °	-121.914509 °
DWR ID	DWR_RD0108_01_s_2016_18				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	11.36	Rating **	C	Issue No.	20
LM End	12.19	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.927325 °	38.938291 °
				-121.913477 °	-121.907516 °
DWR ID	DWR_RD0108_01_s_2016_20				
Comment Code					
C3 : Add appropriate gravel or road base. Grade and compact.					
Inspector Comment					

No Photos

LM Start	12.68	Rating **	M	Issue No.	32
LM End	12.71	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.945376 °	38.945719 °
				-121.906768 °	-121.906773 °
DWR ID	DWR_RD0108_01_s_2017_32				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
150' sloughing section on crown and landside slope. District submitted an application for PL 84-99 assistance.					

Photo 1 of 2 : SP\_2017\_RD0108\_203\_32\_20170503\_00046.jpg



View of sloughing on crown and slope. Spring 2017.

LM Start	<b>12.68</b>	Rating **	M	Issue No.	<b>32 (cont)</b>
LM End	<b>12.71</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP\_2017\_RD0108\_203\_32\_20170503\_00047.jpg



Additional view of sloughing. Spring 2017.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	14.47	Rating **	U	Issue No.	33
LM End	14.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.967062 °	38.967784 °
				-121.923113 °	-121.924148 °
DWR ID	DWR_RD0108_01_s_2017_33				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
400' sloughing section on landside slope. District submitted an application for PL 84-99 assistance.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_33\_20170503\_00048.jpg



View of sloughing on landside slope. Spring 2017.

LM Start	14.76	Rating **	M	Issue No.	21
LM End	14.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.969852 °	38.969852 °
				-121.927023 °	-121.927023 °
DWR ID	DWR_RD0108_01_s_2017_21				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
100' slough section on landside slope. District will repair without PL 84-99 assistance.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_21\_20170503\_00049.jpg



View of sloughing on landside slope. Spring 2017.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	15.46	Rating **	C	Issue No.	22
LM End	15.74	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.976684 °	38.979377 °
				-121.936696 °	-121.940526 °
DWR ID	DWR_RD0108_01_s_2016_22				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

LM Start	16.25	Rating **	M	Issue No.	34
LM End	17.45	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.984453 °	38.997350 °
				-121.947591 °	-121.962543 °
DWR ID	DWR_RD0108_01_s_2017_34				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	17.26	Rating **	U	Issue No.	35
LM End	17.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.995293 °	38.995785 °
				-121.960200 °	-121.960776 °
DWR ID	DWR_RD0108_01_s_2017_35				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
200' sloughing section on landside slope. District submitted an application for PL 84-99 assistance.					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_35\_20170503\_00050.jpg



View of sloughing on landside slope. Spring 2017.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	17.45	Rating **	U	Issue No.	36
LM End	20.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.997350 °	39.031093 °
				-121.962543 °	-121.989451 °
DWR ID	DWR_RD0108_01_s_2017_36				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_203\_36\_20170503\_00051.jpg



Tall grass on landside levee slope, blocking visibility. Spring 2017.

LM Start	18.24	Rating **	M	Issue No.	29
LM End	18.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.005766 °	39.005766 °
				-121.972346 °	-121.972346 °
DWR ID	DWR_RD0108_01_f_2015_29				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 2 : SP\_2017\_RD0108\_203\_29\_20170320\_00012.jpg



Updated view of a site with rodent activity. Fall 2016 inspection.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	18.24	Rating **	M	Issue No.	29 (cont)
LM End	18.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.005766 °	39.005766 °
				-121.972346 °	-121.972346 °
DWR ID	DWR_RD0108_01_f_2015_29				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 2 of 2 : SP\_2017\_RD0108\_203\_29\_20170320\_00013.jpg



View of the animal hole on the waterward side of the levee looking upstream. Fall 2015.

LM Start	19.27	Rating **	M	Issue No.	1
LM End	19.35	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.016727 °	39.017516 °
				-121.985411 °	-121.986374 °
DWR ID	DWR_RD0108_01_s_2016_1				
Comment Code					
Inspector Comment					
2011 - Toe scour at the bottom of a steep bank, large sections of the toe are sliding down. Erosion may be due to the upstream bend. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: CBD_19-2_L]					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Colusa Basin Drain	Left	20.64	05/03/2017 05/03/2017	Zach Jojola

LM Start	<b>20.36</b>	Rating **	M	Issue No.	<b>37</b>
LM End	<b>20.64</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.031515 °	39.033932 °	
			-121.989842 °	-121.993293 °	
DWR ID	DWR_RD0108_01_s_2017_37				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

**\* Location**  
 LS : Land Side    N/A : Not Applicable  
 WS : Water Side  
 CR : Crown

**\*\* Rating**  
 A : Acceptable                      N : Not Inspected/Rated  
 M : Minimally Acceptable        C : Corrected  
 U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
 Ma : Maintenance Deficiency  
 Ob : Design & System Obsolescence  
 En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Castle Properties	Right	0.28	05/02/2017 05/02/2017	Zach Jojola

LM Start	0.01	Rating **	U	Issue No.	2
LM End	0.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.796285 °	38.799029 °
				-121.727879 °	-121.724641 °
DWR ID	DWR_RD0108_02_s_2017_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_590\_2\_20170502\_00006.jpg



Tall grass on waterside levee slope, blocking visibility. Spring 2017.

LM Start	0.02	Rating **	M	Issue No.	6
LM End	0.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.796355 °	38.796355 °
				-121.727721 °	-121.727721 °
DWR ID	DWR_RD0108_02_f_2015_6				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Mound does not look fresh but seems to have come from the rodent hole.					

Photo 1 of 3 : SP\_2017\_RD0108\_590\_6\_20170320\_00002.jpg



Mound next to rodent hole is more than 2 cubic feet of material.

LM Start	<b>0.02</b>	Rating **	M	Issue No.	<b>6 (cont)</b>
LM End	<b>0.02</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : SP\_2017\_RD0108\_590\_6\_20170320\_00003.jpg



Perspective view of the rodent hole on the waterward side of the levee looking upstream. Spring 2016.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Castle Properties	Right	0.28	05/02/2017 05/02/2017	Zach Jojola

LM Start	0.02	Rating **	M	Issue No.	6 (cont)	
LM End	0.02	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Animal Control			38.796355 °		38.796355 °
				-121.727721 °		-121.727721 °
DWR ID	DWR_RD0108_02_f_2015_6					
Comment Code						
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.						
Inspector Comment						
Mound does not look fresh but seems to have come from the rodent hole.						

Photo 3 of 3 : SP\_2017\_RD0108\_590\_6\_20170320\_00004.jpg



Another hole is on top of the crown. Spring 2016.

LM Start	0.03	Rating **	C	Issue No.	1
LM End	0.03	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.796447 °	38.796447 °
				-121.727487 °	-121.727487 °
DWR ID	DWR_RD0108_02_f_2016_1				
Comment Code					
C3 : Add appropriate gravel or road base. Grade and compact.					
Inspector Comment					
Crown surface is damaged due to vehicular activity.					

No Photos

LM Start	0.10	Rating **	U	Issue No.	3
LM End	0.27	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.797130 °	38.799027 °
				-121.726712 °	-121.724641 °
DWR ID	DWR_RD0108_02_s_2017_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP\_2017\_RD0108\_590\_3\_20170502\_00007.jpg



Tall grass on landside levee slope, blocking visibility. Spring 2017.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

### Reclamation District No. 0108 River Farms

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Castle Properties	Right	0.28	05/02/2017 05/02/2017	Zach Jojoba

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---